

FIG. 1




FIG. 2






FIG. 3




090913-1000

FIG. 4


FOURTH STEP



FIFTH STEP



SIXTH STEP



TO SEVENTH STEP

09698185 103000

[illegible]

FIG. 6




FIG. 7




FIG. 8




FIG. 9






FIG. 10



000186600



000186600




FIG. 13




FIG. 14




FIG. 15




FIG. 17





FIG. 18



09698495-103000

FIG. 19






FIG. 20



096275-1000



096275-1000




FIG. 27





FIG. 28



SECRET

THE

[illegible]

FIG. 31




FIG. 32




FIG. 33a




FIG. 33b




FIG. 34a




FIG. 34b





FIG. 35



050918-103000

FIG. 36




FIG. 37




FIG. 38




FIG. 39a




FIG. 39b




FIG. 39c




FIG. 40





FIG. 41



PHYSICAL VALUES AND SPUTTER RESISTANCE OF STRESS RELAXATION LAYER CANDIDATE MATERIAL (X: OCCURRENCE OF CRACKS, △: OCCURRENCE OF WRINKLE, ○: NO ABNORMALITY)